

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S95W /33SESW

Location ID: 334877



Photo #9198 From entrance to location.



Photo #9199 From entrance to location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S95W /33SESW

Location ID: 334877



Photo #9200 From entrance to location.



Photo #9202 Loadline open ended.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S95W /33SESW

Location ID: 334877



Photo #9213 Calibration cards not conspicuously posted



Photo #9202 Loadline open ended.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S95W /33SESW

Location ID: 334877



Photo #9211 Multiple tanks missing required information.



Photo #9212 Multiple tanks missing required information.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S95W /33SESW

Location ID: 334877



Photo #9215 Unused equipment.



Photo #9214 Chemical tank open ended.