

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2023

Submitted Date:

03/03/2023

Document Number:

701006491**FIELD INSPECTION FORM**Loc ID 337923 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289695	WELL	PR	08/01/2019	GW	125-10767	SHIVELY 12-4	PR

**General Comment:**Routine Inspection

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead, VGS and meter run		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Weatherford unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Kohler gas engine		
Corrective Action:		Date:	

Type: Vertical Separator	# 0		
Comment:			
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	289695	Type:	WELL	API Number:	125-10767	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Kitzmiller 1-4 and Shively 12-4) 1135' NE @ 39.830460/-102.199300								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Fail			

Comment: [Access is impassable](#)Corrective Action: [Repair and maintain access to wellhead](#)

Date: 03/27/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403343323	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6047015">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6047015</a>