

# Inspection Photos

March 14, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334907

Location Name: COUEY-67S92W/8NESE

Inspection Document #: 702801370

Garfield County, CO

NESE Section 8 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: COUEY-67S92W/8NESE  
Location ID: 334907



**Photo 1.** Photo taken from the entrance shows an overview of the location.



Inspection Photos  
Location Name: COUEY-67S92W/8NESE  
Location ID: 334907



Photo 2. Photos show production areas.





Inspection Photos  
Location Name: COUEY-67S92W/8NESE  
Location ID: 334907



**Photo 3.** Photos shows two (2) unmarked anchors.



Inspection Photos  
Location Name: COUEY-67S92W/8NESE  
Location ID: 334907



**Photo 4.** Photo shows a chemical tank with labeling.



Inspection Photos  
Location Name: COUEY-67S92W/8NESE  
Location ID: 334907



**Photo 5.** Photos show interim areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801370