

# Inspection Photos

March 14, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334786

Location Name: COUEY-67S92W/8NWNE

Inspection Document #: 702801374

Garfield County, CO

NWNE Section 8 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: COUEY-67S92W/8NWNE  
Location ID: 334786



**Photo 1.** Photo taken from the entrance shows an overview of the location.





Inspection Photos  
Location Name: COUEY-67S92W/8NWNE  
Location ID: 334786



**Photo 2.** Photo taken from the entrance shows an overview of the eastern portion of the location.





Inspection Photos  
Location Name: COUEY-67S92W/8NWNE  
Location ID: 334786



**Photo 3.** Photos show western production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801374

Inspection Photos  
Location Name: COUEY-67S92W/8NWNE  
Location ID: 334786



**Photo 4.** Photo shows eastern production areas.





Inspection Photos  
Location Name: COUEY-67S92W/8NWNE  
Location ID: 334786



**Photo 5.** Photos show an example of interim areas.

