

Inspection Photos

API: 071-09267

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/9/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 3/9/2023

Inspection Photos



Photo 1. The culverts at the creek crossing along the main road are filled in with debris restricting water flow. Culverts need to be cleaned out.



Inspection Photos



Photo 2. Facing southwest toward the location. The gate to the location is laying on the ground and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 3/9/2023

Inspection Photos



Photo 3. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 3/9/2023

Inspection Photos



Photo 4. The pit liner still remains torn and water has not been lowered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 3/9/2023