

Inspection Photos

API: 071-08325

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/20/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08325 | Date: 3/20/2023

Inspection Photos



Photo 1. Facing south toward the access road. There are vehicle ruts and the road is not compacted and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08325 | Date: 3/20/2023

Inspection Photos



Photo 2. There is signs of vehicle tracking onto the county road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08325 | Date: 3/20/2023

Inspection Photos



Photo 3. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08325 | Date: 3/20/2023

Inspection Photos



Photo 4. There is oil in the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08325 | Date: 3/20/2023

Inspection Photos



Photo 5. Sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08325 | Date: 3/20/2023