

Interim and Stormwater Inspection

March 13, 2023

Operator: Verdad Resources # 10651

Location ID: 319961

Inspection Document #:709400075

Adams County

NENW, Section 8, 1S65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Bergman 1 & 32-8

Location ID: 319961



Photo 1. Photo taken of location sign.



Photo 2. Photo taken of leaking bull plug on back side of holding tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400075

Inspection Photos
Location Name: Bergman 1 & 32-8
Location ID: 319961

Mar 13, 2023 at 2:48:09 PM
25900 E 160th Ave
Brighton CO 80603
United States

Mar 13, 2023 at 2:48:14 PM
25900 E 160th Ave
Brighton CO 80603
United States

Photo 3. Photo taken of weedy unstabilized area on location

Photo 4. See photo 3 comments.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400075