

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277



Photo 1 – Tank Battery

Photo 2 – Water Tank – Capacity Label

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277



Photo 3 – Tank Battery Signs

Photo 4 – Separator

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277




Photo 5 – Tags/Labels faded or weather off and broke



Photo 6 – Gas Meter

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277





Photo 7 – Gas Meter

Photo 8 – Gas Meter – Flow Rate

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277




Photo 9 – Gas Meter – Yesterday’s Volume