

Inspection Photos
Location Name: Wolf 36-3624H
Location ID: 426841



Photo 1 – Signs at Entrance – No Fundare Contact Info
posted



Photo 2 – Tank Battery

Inspection Photos
Location Name: Wolf 36-3624H
Location ID: 426841



Photo 3 – Tank Battery Sign – No Fundare Info Posted



Photo 4 – Heater Treater – No Fundare Info posted

Inspection Photos
Location Name: Wolf 36-3624H
Location ID: 426841



Photo 5 – ECD and Flare have been removed



Photo 6 – Pipes and Fittings

Inspection Photos
Location Name: Wolf 36-3624H
Location ID: 426841



Photo 7 – Pumping Unit




Photo 8– Wellhead – TA'd. No Fundare Info posted