

# Inspection Photos

3/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location #335795

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335795



**Photo 1:** Photo provides an overview of the working pad. Photo also example showing BMPs on the Location, including vehicle tracking control measures, are missing or insufficient to minimize erosion, degradation and sediment transport during wet conditions.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335795



**Photo 2:** Photos 2-5 examples showing BMPs, including vehicle tracking control measures, are missing or insufficient on the Location and access road, in order to stabilize, as well as to minimize erosion, degradation and sediment transport during wet conditions.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335795



**Photo 3:** See comments under photo 2.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335795



**Photo 4:** See comments under photo 2. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335795



**Photo 5:** See comments under photo 2. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335795



**Photo 6:** Photo shows liner appears to have been repaired.