

Inspection Photos

3/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location #324198

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #324198



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the working pad area from south, southwest, northwest to north. Photos 1-3 also provide examples showing BMPs, including vehicle tracking control measures, are missing or insufficient to stabilize, as well as to minimize erosion, degradation and sediment transport during wet conditions.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #324198



March 21, 2023



March 21, 2023

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #324198



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #324198



Photo 4: Photo taken from the tank battery. Photo shows repairs appear to have been made to the secondary containment liner.

