

TEP ROCKY MOUNTAIN LLC, CLOUGH-66S94W/22SENE

Location # 335110




Wellheads – Photo #01493



Separators – Photo #01485

TEP ROCKY MOUNTAIN LLC, CLOUGH-66S94W/22SENE

Location # 335110



Tank Battery – Photo #01489



Debris – Photo #01488



TEP ROCKY MOUNTAIN LLC, CLOUGH-66S94W/22SENE

Location # 335110



Trash – Photo #01499



Casing Flange Leak – Photo #01494



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP ROCKY MOUNTAIN LLC, CLOUGH-66S94W/22SENE

Location # 335110



Lack of Stabilization – Photo #01497



Transport of Sediment – Photo #01492