

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Location ID: 323833



Photo #9233 From entrance to location.



Photo #9234 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Location ID: 323833



Photo #9235 From entrance to location.



Photo #9239 Loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NWSW

Location ID: 323833

Network:Mar 13, 2023 at 12:48:06 PM MD
CC



Photo #9241 Calibration cards not conspicuously posted.