

**FORM  
43**Rev  
05/21**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109**OGCC RECEPTION****Receive Date:****01/04/2023****Document Number:****403279015****ANALYTICAL SAMPLE DATA SUBMITTAL FORM**Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

**Operator Information**

OGCC Operator Number: 47120 Contact Person: Erik Mickelson  
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-4306  
Address: P O BOX 173779 Fax: ( )  
City: DENVER State: CO Zip: 80217-3779 Email: Erik\_Mickelson@oxy.com

**Identification Information**

API Number: 05 - - OGCC Facility ID: 323420 Initial Form 19 or 27 Document number: -  
Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION  
Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6  
County: WELD Field Name: WATTENBERG  
Federal, Indian or State Lease Number: -

**Information Submitted By:**

Company Name: Absaroka Agent Name: Tanya Cude Title: Environmental Scientist  
Phone Number: 352-318-4034 Email: Tanya.Cude@Absarokasolutions.com

**Rule 909.J Inspection Information**Date the Pit was Inspected -On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 752922 Facility Name: Hochmiller\_84411 Facility Type: Commercial  
Location: QtrQtr: NWNE Sec: 32 Twp: 3N Range: 65W Meridian: 6  
County Name: WELD Latitude: 40.188001 Longitude: -104.683636

**Sample Information:**

The following Sample Information has been reviewed by the COGCC:

Batch ID: 106516 Document Name: TB File Name: 2022\_09\_20\_Hochmiller 84411--A Trip Blank SGS COGCC.xls  
SampleType: - Matrix: -  
Facility ID: 752922 Sample ID: 644849 Sample Name: Hochmiller 84411--A Sample Date: 09/20/2022  
Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill  
Project Number: - Remediation Number: - Complaint Number: - NOAV Number: -  
Inspection Number: - Spill Number: - Laboratory: Accutest Lab Sample ID: DA49305-1

Batch ID: 106519		Document Name: NG4		File Name: 2022_09_20_Hochmiller 84411--A Isotech NG4 COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 644853	Sample Name: Hochmiller 84411--A		Sample Date: 09/20/2022	
Collection Point: COM	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 843150		

  

Batch ID: 106517		Document Name: SGS		File Name: 2022_09_20_Hochmiller 84411--A SGS COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 644850	Sample Name: Hochmiller 84411--A		Sample Date: 09/20/2022	
Collection Point: COM	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA49303-1		

  

Batch ID: 106519		Document Name: NG4		File Name: 2022_09_20_Hochmiller 84411--A Isotech NG4 COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 644852	Sample Name: Hochmiller 84411--A		Sample Date: 09/20/2022	
Collection Point: COM	Matrix: GAS	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 843150		

  

Batch ID: 106518		Document Name: SIW		File Name: 2022_09_20_Hochmiller 84411--A Isotech SIW COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 644851	Sample Name: Hochmiller 84411--A		Sample Date: 09/20/2022	
Collection Point: COM	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 843148		

### Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
752922	403279026	2022_09_20_Hochmiller 84411--A Trip Blank SGS.pd	Analytical Laboratory Report	PDF
752922	403279027	2022_09_20_Hochmiller 84411--A SGS.pdf	Analytical Laboratory Report	PDF
752922	403279035	2022_09_20_Hochmiller 84411--A Isotech SIW.pdf	Analytical Laboratory Report	PDF
752922	403279029	2022_09_20_Hochmiller_84411_A_Loc.jpg	Photographs	JPG
752922	403279030	2022_09_20_Hochmiller_84411_A_PrePostPurge.jpg	Photographs	JPG
752922	403279028	2022_09_20_Hochmiller_84411_A_FS_COGCC.pdf	Field Data Report	PDF
752922	403279032	2022_09_20_Hochmiller_84411_A_Wellhead.jpg	Photographs	JPG
752922	403279038	2022_09_20_Hochmiller 84411--A Isotech NG4.pdf	Analytical Laboratory Report	PDF
752922	403279031	2022_09_20_Hochmiller_84411_A_Spigit.jpg	Photographs	JPG

### Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	03/23/2023
Total: 1 comment(s)		