

Inspection Photos

API: 071-09013

Operator: WAPITI OPERATING LLC

Inspection Date: 3/22/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09013 | Date: 3/22/2023

Inspection Photos



Photo 1. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09013 | Date: 3/22/2023

Inspection Photos



Photo 2. Sign is posted near the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09013 | Date: 3/22/2023