

Inspection Photos

Location: McCartney Engineering LLC / SJ Warren #1 Tank Battery

Facility ID: 455236



Photo 1 – Sign present



Photo 2 – Spill present on soil

Inspection Photos

Location: McCartney Engineering LLC / SJ Warren #1 Tank Battery

Facility ID: 455236



Photo 3 – Wildlife protection not adequate



Photo 4 – Wildlife protection not adequate

Inspection Photos

Location: McCartney Engineering LLC / SJ Warren #1 Tank Battery

Facility ID: 455236



Photo 5 – Oily waste present on soil



Photo 6 – Oily waste present and unnecessary trash on site

Inspection Photos

Location: McCartney Engineering LLC / SJ Warren #1 Tank Battery

Facility ID: 455236



Photo 7 – Oily waste observed on soil