

Inspection Photos
Location Name: Parmlee #3
Location ID: 327604



Photo 1 – Well Sign



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Parmlee #3
Location ID: 327604



Photo 3 – Wellhead



Photo 4 – Hardline plumbed into Wellhead

Inspection Photos
Location Name: Parmlee #3
Location ID: 327604



Photo 5 – Hardline



Photo 6 – Produced Water at Wellsite. No berm