



ejb

LOCATION SWSW 13-35-55W FIELD 1 ESCALERO
OPERATOR J. W. NYLAND COUNTY WASHINGTON
WELL NAME #1 GRADE FORMATION _____

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____
BOP'S _____ DEPTH _____ WOC _____
CONTACT _____ CMT VOL _____ RETURNS _____
ADEQUATE AQUIFER PROTECTION? _____
COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: _____ PRODUCTION STRING: _____
CBL CHECKED? _____ DEPTH _____ STAGED _____
WATER DISPOSAL METHOD _____
PITS: PERMIT _____ TDS _____ SKIM TANK _____
DIMENSION: _____ SCREEN: _____ LINER: _____

LEASE SIGN: _____ TANK ID: _____ FENCED? _____
SURFACE EQUIPMENT: _____

DATE OF FINAL P&A INSPECTION 9/9/86

PLUG 1	<u>SX @</u>	SURFACE RECLAIMED? <u>Y</u>
PLUG 2	<u>SX @</u>	SITE CLEAN? <u>Y</u>
PLUG 3	<u>SX @</u>	LANDOWNER RELEASE? _____

INSPECTOR R. VACLAVIK

PITS LOADED
NO PIPE
PLOWED FIELD

05-121-10231 Y