



00400473

## LEASE INSPECTION FORM

Operator J.W. Nylund Date 1/24/86  
Lease Name & No. Gode 1 Field \_\_\_\_\_  
Tank Battery No. \_\_\_\_\_ County Washington  
Location SWSW 13-3S-55W  
Legal Description \_\_\_\_\_  
Type of Inspection P+A check  
Water Inflow \_\_\_\_\_ (Bbls. Per Day)

## RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)  
Type of Tank

SKIM TANK None

Pit No. 1 None

Pit No. 2 \_\_\_\_\_

Pit No. 3 \_\_\_\_\_

ADDITIONAL PITS \_\_\_\_\_

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

hole plugged but pits are still open.  
Mel Christianson of Nylund's office said pits would  
be filled in this spring.

RECOMMENDED ACTION (If Required) None

INSPECTOR SP