

TEP
Miller 33B
Location # 335040



Access road show lack of stabilization



Entrance to location



TEP
Miller 33B
Location # 335040



location



location



TEP
Miller 33B
Location # 335040



location



location



TEP
Miller 33B
Location # 335040



Unused chemical tank/ disconnected



Label is illegible



TEP
Miller 33B
Location # 335040



Stored hose



Lack of stabilization/compaction

TEP
Miller 33B
Location # 335040



Lack of stabilization/compaction



Lack of stabilization/compaction



TEP
Miller 33B
Location # 335040



Some paraffin leaking out of hose



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources