

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403356413

Date Received:
03/27/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5200
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Mike Storey	970-939-6353	mstorey@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 709400089
Inspection Date: 03/15/2023 FIR Submit Date: 03/21/2023 FIR Status:

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC Company Number: 10459
Address: 370 17TH STREET SUITE 5200
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320612

Location Name: WENZEL-61S65W Number: 30NWSW County:
Qtrqr: NWS Sec: 30 Twp: 1S Range: 65W Meridian: 6
W
Latitude: 39.934290 Longitude: -104.712550

FACILITY - API Number: 05-001-00 Facility ID: 320612

Facility Name: WENZEL-61S65W Number: 30NWSW
Qtrqr: NWS Sec: 30 Twp: 1S Range: 65W Meridian: 6
W
Latitude: 39.934290 Longitude: -104.712550

CORRECTIVE ACTIONS:

1 CA# 168360

Corrective Action: Comply with Rule 606.d. Date: 03/24/2023

Response: CA COMPLETED Date of Completion: 03/27/2023

Operator Comment: Trash and unused equipment have been removed from location to comply with Rule 606.d.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 3/27/2023 8:13:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403356426	Inspection Photos
-----------	-------------------

Total Attach: 1 Files