

Inspection Photos

3/24/2023

Operator: CHEVRON USA INC - 16700

Location #314696

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 1: Photos 1-5 provide examples showing BMPs to stabilize, as well as to minimize degradation, tracking and off-site sediment transport remain missing or insufficient. 6 foot measuring stick for reference.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696




Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 3: See comments under photo 1. Photo also shows an additional tank not previously observed has been brought onto the Location; tank missing signage per Rule 605.h.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 5: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 6: See comments under photo 1. Photo shows tracking/rutting and off-site sediment transport onto Highway 64 from the access road has continued

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



March 24, 2023



March 24, 2023

Photo 7: Photos 7-9 provide examples showing soils stockpiles that have been pushed beyond the perimeter of the working pad, therefore expanding the disturbance of the Location. Photos show BMPs to minimize erosion, degradation and sediment transport remain missing or insufficient.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 8: See comments under photo 7.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



March 24, 2023

Photo 9: See comments under photo 7.

Location #314696



Photo 10: Photo shows wellhead has been re-assembled. Cellar cover(s) have been replaced.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 11: Photos shows stained soils around production equipment.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location #314696



Photo 12: Photo shows the 2nd point of access that was developed due to off-site vehicle travel from the Location/access road. Photo shows Operator has placed fencing at the disturbance to prevent further offsite travel.