

# Final Reclamation Inspection

March 23, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 328962

Inspection Document #: 697504580

Weld County, CO

NWNW Section 23 T4N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: HSR-GREENBERG-64N66W 23NWNW

Location ID: 328962



**Photo 1.** Photo taken from the well location, facing West. Photo illustrates location has been seeded and in process of establishing.



**Photo 2.** Photo taken from the well location, facing Northeast. See comments under Photo 1.



## Inspection Photos

Location Name: HSR-GREENBERG-64N66W 23NWNW

Location ID: 328962



**Photo 3.** Photo taken from the tank battery, facing North. See comments under Photo 1.

Note- tank battery has an open Rem. Project #18828.



**Photo 4.** Photo taken from the tank battery, facing Southeast. Photo illustrates 1 of the 12 groundwater monitoring wells that have been installed.

Inspection Photos  
Location Name: HSR-GREENBERG-64N66W 23NWNW  
Location ID: 328962



**Photo 5.** Photo illustrates the well location (red circle) and off-location flowline to the the tank battery.