

# Inspection Photos

March 23, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335509

Location Name: JOHNSON-66S94W/30SWSE

Inspection Document #: 702801380

Garfield County, CO

SWSE Section 30 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: JOHNSON-66S94W/30SWSE  
Location ID: 335509



**Photo 1.** Photo shows production areas.



Inspection Photos  
Location Name: JOHNSON-66S94W/30SWSE  
Location ID: 335509



**Photo 2.** Photo shows storage of equipment not necessary for production operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801380

Inspection Photos  
Location Name: JOHNSON-66S94W/30SWSE  
Location ID: 335509



**Photo 3.** Photos show interim areas appear to be in production for annual crops (left) and are vegetated with perennial grasses directly adjacent to the working pad area (right).

