

Inspection Photos

March 23, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335487

Location Name: POTTER-66S94W/31NENW

Inspection Document #: 702801384

Garfield County, CO

NENW Section 31 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: POTTER-66S94W/31NENW
Location ID: 335487



Photo 1. Photo taken from the entrance shows an overview of the location.

Inspection Photos
Location Name: POTTER-66S94W/31NENW
Location ID: 335487



Photo 2. Photo shows lack of pad stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801384

Inspection Photos
Location Name: POTTER-66S94W/31NENW
Location ID: 335487



Photo 3. Photo shows an unmarked anchor at the north of the location.



Inspection Photos
Location Name: POTTER-66S94W/31NENW
Location ID: 335487



Photo 4. Photo shows interim areas to the north of the location, including Russian knapweed (List B Noxious).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801384

Inspection Photos
Location Name: POTTER-66S94W/31NENW
Location ID: 335487



Photo 5. Photo shows interim areas. Vegetation is heavily grazed.

