

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /27NESW.

Location ID: 335094



Photo #9377 From entrance to location.



Photo #9378 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /27NESW.

Location ID: 335094



Photo #9379 From entrance to location.



Photo #9382 Undesirable Plant Species in tank containment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /27NESW.

Location ID: 335094



Photo #9381 Loadline open ended.



Photo #9383 Calibration cards not conspicuously posted.