

Interim and Stormwater Inspection

March 23, 2023

Operator: Kerr McGee Oil & Gas # 47120

Location ID: 241669

Inspection Document #:709400110

Weld County

NENE, Section 20, 2N66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Paul Schmidt "B"

Location ID: 241669



Photo 1. Photo taken of sign on location.



Photo 2. Photo of rocks left on site from drilling pad construction.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400110

Inspection Photos

Location Name: Paul Schmidt "B"

Location ID: 241669



Mar 23, 2023 at 10:09:18 AM
Fort Lupton CO 80621
United States

Photo 3. Photo taken of weeds on site.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400110