

Inspection Photos  
Location Name: Cosslett #6  
Location ID: 213434



Photo 1 Well head



Photo 2 Trash

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 3 Open excavation going to Cosslett 1**



**Photo 4 Excavation material not BMP**

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 5 Open excavation looking North no BMP's in creek crossing**



**Photo 6 Pipeline facing west toward Cosslett 1**

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 7 Creek crossing**



**Photo 8 Tie point on east side of Cosslett 6 next to housing community.**

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 9 Disturbed area next to housing community**



**Photo 10 Pipeline disturbed area between tie in point and Cosslett 6**

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 11 open excavation stock pile material no BMP' in wetland**



**Photo 12 material not protected in wet land**

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 13 Pipe line disturbed area**



**Photo 14 pipeline disturbed area**

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 15 Disturbance toward Cosslett 6**



**Photo 16 Tie in point**

**Inspection Photos**  
**Location Name: Cosslett #6**  
**Location ID: 213434**



**Photo 17 unused equipment Steel pipe**



**Photo 18 unused equipment poly pipe.**