

Centennial #1  
Land X  
Centennial #2  
Land X

## COLORADO OIL AND GAS CONSERVATION COMMISSION

## UIC Field Report



00325590

Date: 8-7-85

Site Inspection



Witness Mechanical Integrity Test

Well Name: Centennial Landacker #1Field: West ForkLocation: SWSE Sec 18 Twp 35 Rng 55WOperator: Berry Energy

Last Reported injection press. \_\_\_\_\_

Max. press. allowed. \_\_\_\_\_

Well Type: ☐ Tubing-packer

Zone: \_\_\_\_\_

☐ Casing Disposal☐ Dual Completion

Status at time of inspection:

Injecting 0 (vac) psi

Not Injecting \_\_\_\_\_ psi

Tubing-Casing Annulus Pressure 0 psi

Braidenhead Pressure \_\_\_\_\_ psi

Mechanical Integrity Test \_\_\_\_\_ 0 min.

\_\_\_\_\_ 5 min.

\_\_\_\_\_ 10 min.

\_\_\_\_\_ 15 min.

Pressure change during test \_\_\_\_\_ psi

Chart used ☐ Yes ☒ NoRemarks: backside was on avacuum when first openedbled down, tried to pressureup, wouldn't go, broke offgauge & backside was blowingyet tubing remained on avacuum

## Wellbore Diagram





