

Inspection Photos  
Location Name: Miller 3-26A  
Location ID: 331564



Photo 1 WH sign.

Photo 2 WH

Inspection Photos  
Location Name: Miller 3-26A  
Location ID: 331564



Photo 3 TB sign.

Photo 4 TB.

**Inspection Photos**  
**Location Name: Miller 3-26A**  
**Location ID: 331564**



**Photo 5 Horizontal Heated Separator.**



**Photo 6 Gas Meter Runs.**

**Inspection Photos**  
**Location Name: Miller 3-26A**  
**Location ID: 331564**



**Photo 7 ECD.**