

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 226-27 pad

Location ID: 324161



Photo # 3568 From entrance to location



Photo # 3569 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 226-27 pad

Location ID: 324161



Photo # 3571 Debris



Photo # 3576 Chemical containment full/Failure to maintain chemical BMP

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 226-27 pad

Location ID: 324161



Photo # 3580 Chemical containment full/Failure to maintain chemical BMP