

# LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location # 452797



**Location – Photo #01667**

**Wellheads – Photo #01668**

# LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location # 452797



Separator – Photo #01673



Tank Battery – Photo #01681

# LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location # 452797



ECD – Photo #01683



Inadequate Chemical Containment – Photo #01669

# LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location # 452797



**Lack of Stabilization – Photo #01684**



**Site Degradation/Transport of Sediment – Photo #01685**

# LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad

Location # 452797



**Lack of Stabilization – Photo #01672**