

LARAMIE ENERGY LLC, Piceance/29-07

Location # 334436



Wellheads/Chemical Tanks – Photo #01687



Separators – Photo #01693

LARAMIE ENERGY LLC, Piceance/29-07

Location # 334436



Tank Battery – Photo #01696



ECD – Photo #01703

LARAMIE ENERGY LLC, Piceance/29-07

Location # 334436



Pig Station – Photo #01701



**Inadequate Chemical Secondary Containment –
Photo #01688**



LARAMIE ENERGY LLC, Piceance/29-07

Location # 334436



Degradation/Transport of Sediment – Photo #01689



Degradation/Transport of Sediment – Photo #01690

LARAMIE ENERGY LLC, Piceance/29-07

Location # 334436



Lack of Stabilization – Photo #01691



Lack of Stabilization – Photo #01692