

LARAMIE ENERGY LLC, Piceance/28-11 Pad

Location # 438499



Wellheads – Photo #01716



Separators – Photo #01708

LARAMIE ENERGY LLC, Piceance/28-11 Pad

Location # 438499



Tank Battery – Photo #01705



**Chemical Tanks/Inadequate Secondary Containment
– Photo #01717**



LARAMIE ENERGY LLC, Piceance/28-11 Pad

Location # 438499



**Chemical Tanks/Inadequate Secondary Containment
– Photo #01718**



ECD – Photo #01713

LARAMIE ENERGY LLC, Piceance/28-11 Pad

Location # 438499



Pig Station – Photo #01711



Degradation/Transport of Sediment – Photo #01720

LARAMIE ENERGY LLC, Piceance/28-11 Pad

Location # 438499



Lack of Stabilization – Photo #01707