

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2023

Submitted Date:

03/29/2023

Document Number:

708300234

FIELD INSPECTION FORM

Loc ID 311764	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 17 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																
Operator Information: OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1700 LINCOLN ST STE 3950 City: DENVER State: CO Zip: 80203				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE																																																																																																
Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Kellerby, Shaun</td> <td></td> <td>shaun.kellerby@state.co.us</td> <td></td> </tr> <tr> <td>, LARAMIE</td> <td></td> <td>cogccnotifications@laramie-energy.com</td> <td></td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment	Kellerby, Shaun		shaun.kellerby@state.co.us		, LARAMIE		cogccnotifications@laramie-energy.com																																																																																					
Contact Name	Phone	Email	Comment																																																																																																	
Kellerby, Shaun		shaun.kellerby@state.co.us																																																																																																		
, LARAMIE		cogccnotifications@laramie-energy.com																																																																																																		
Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>295038</td><td>WELL</td><td>PR</td><td>10/11/2010</td><td>GW</td><td>077-09553</td><td>NVEGA 23-211</td><td>PR</td></tr> <tr><td>295039</td><td>WELL</td><td>PR</td><td>11/21/2010</td><td>GW</td><td>077-09554</td><td>NVEGA 23-111</td><td>PR</td></tr> <tr><td>295040</td><td>WELL</td><td>PR</td><td>05/01/2022</td><td>GW</td><td>077-09555</td><td>NVEGA 23-214</td><td>PR</td></tr> <tr><td>295632</td><td>WELL</td><td>PR</td><td>02/01/2020</td><td>GW</td><td>077-09616</td><td>NVEGA 23-221</td><td>PR</td></tr> <tr><td>295633</td><td>WELL</td><td>PR</td><td>08/01/2017</td><td>GW</td><td>077-09615</td><td>NVEGA 23-224</td><td>PR</td></tr> <tr><td>295634</td><td>WELL</td><td>PR</td><td>12/12/2010</td><td>GW</td><td>077-09614</td><td>NVEGA 23-114</td><td>PR</td></tr> <tr><td>295635</td><td>WELL</td><td>PR</td><td>07/01/2017</td><td>GW</td><td>077-09613</td><td>NVEGA 23-311</td><td>PR</td></tr> <tr><td>295637</td><td>WELL</td><td>PR</td><td>12/12/2012</td><td>GW</td><td>077-09611</td><td>NVEGA 23-121</td><td>PR</td></tr> <tr><td>295638</td><td>WELL</td><td>PR</td><td>12/01/2017</td><td>GW</td><td>077-09610</td><td>NVEGA 23-124</td><td>PR</td></tr> <tr><td>295640</td><td>WELL</td><td>PR</td><td>01/04/2011</td><td>GW</td><td>077-09608</td><td>NVEGA 23-321</td><td>PR</td></tr> <tr><td>295641</td><td>WELL</td><td>PR</td><td>08/01/2018</td><td>GW</td><td>077-09607</td><td>NVEGA 23-314</td><td>PR</td></tr> </tbody> </table>					Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	295038	WELL	PR	10/11/2010	GW	077-09553	NVEGA 23-211	PR	295039	WELL	PR	11/21/2010	GW	077-09554	NVEGA 23-111	PR	295040	WELL	PR	05/01/2022	GW	077-09555	NVEGA 23-214	PR	295632	WELL	PR	02/01/2020	GW	077-09616	NVEGA 23-221	PR	295633	WELL	PR	08/01/2017	GW	077-09615	NVEGA 23-224	PR	295634	WELL	PR	12/12/2010	GW	077-09614	NVEGA 23-114	PR	295635	WELL	PR	07/01/2017	GW	077-09613	NVEGA 23-311	PR	295637	WELL	PR	12/12/2012	GW	077-09611	NVEGA 23-121	PR	295638	WELL	PR	12/01/2017	GW	077-09610	NVEGA 23-124	PR	295640	WELL	PR	01/04/2011	GW	077-09608	NVEGA 23-321	PR	295641	WELL	PR	08/01/2018	GW	077-09607	NVEGA 23-314	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																													
295038	WELL	PR	10/11/2010	GW	077-09553	NVEGA 23-211	PR																																																																																													
295039	WELL	PR	11/21/2010	GW	077-09554	NVEGA 23-111	PR																																																																																													
295040	WELL	PR	05/01/2022	GW	077-09555	NVEGA 23-214	PR																																																																																													
295632	WELL	PR	02/01/2020	GW	077-09616	NVEGA 23-221	PR																																																																																													
295633	WELL	PR	08/01/2017	GW	077-09615	NVEGA 23-224	PR																																																																																													
295634	WELL	PR	12/12/2010	GW	077-09614	NVEGA 23-114	PR																																																																																													
295635	WELL	PR	07/01/2017	GW	077-09613	NVEGA 23-311	PR																																																																																													
295637	WELL	PR	12/12/2012	GW	077-09611	NVEGA 23-121	PR																																																																																													
295638	WELL	PR	12/01/2017	GW	077-09610	NVEGA 23-124	PR																																																																																													
295640	WELL	PR	01/04/2011	GW	077-09608	NVEGA 23-321	PR																																																																																													
295641	WELL	PR	08/01/2018	GW	077-09607	NVEGA 23-314	PR																																																																																													
General Comment: <div style="height: 150px; border: 1px solid black;"></div>																																																																																																				

COGCC Inspection Report Summary

On 3/28/2023 at approximately 15:00, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, NVega/4B at Location ID #311764 in Mesa County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Tank battery berm capacity inadequate due to snow build-up in containment

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 11		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal		Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Inadequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Tank battery berm capacity inadequate due to snow build-up in containment				
Corrective Action:	Comply with Rule 603				Date: 04/29/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	295038	Type:	WELL	API Number:	077-09553	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295039	Type:	WELL	API Number:	077-09554	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295040	Type:	WELL	API Number:	077-09555	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295632	Type:	WELL	API Number:	077-09616	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295633	Type:	WELL	API Number:	077-09615	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295634	Type:	WELL	API Number:	077-09614	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295635	Type:	WELL	API Number:	077-09613	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295637	Type:	WELL	API Number:	077-09611	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	295638	Type:	WELL	API Number:	077-09610	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	295640	Type:	WELL	API Number:	077-09608	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	295641	Type:	WELL	API Number:	077-09607	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
		Gravel				
		Culverts				
Berms						
		Ditches				

Comment: Lease road lacks stabilization which may lead to future tracking issues

Corrective Action: Unable to inspect all location BMPs due to snow cover

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300235	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6066193