

Inspection Photos

March 23, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335259

Location Name: COOK-66S94W/28NESW

Inspection Document #: 702801390

Garfield County, CO

NESW Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: COOK-66S94W/28NESW
Location ID: 335259



Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: COOK-66S94W/28NESW
Location ID: 335259



Photo 2. Photos show production areas

Inspection Photos
Location Name: COOK-66S94W/28NESW
Location ID: 335259



Photo 3. Photo shows an unmarked anchor at the west of the location.

Inspection Photos
Location Name: COOK-66S94W/28NESW
Location ID: 335259



Photo 4. Photos show interim areas.

