

Inspection Photos

API: 071-08698

Operator: OGRIS OPERATING LLC

Inspection Date: 3/29/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08698 | Date: 3/29/2023

Inspection Photos



Photo 1. Facing west toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08698 | Date: 3/29/2023

Inspection Photos



Photo 2. Panels are installed around wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08698 | Date: 3/29/2023

Inspection Photos



Photo 3. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08698 | Date: 3/29/2023