

# Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 429828

Location Name: Duggan/RWF 14-29

Inspection Document #: 702801404

Garfield County, CO

Lot 5 Section 29 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 1.** Photo taken from the west shows an overview of the location.




Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 2.** Photos show production areas.



Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 3.** Photo shows leaky chemical injection units and stained soil at the wells.





Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 4.** Photo shows lack of stabilization on the access road to the south of the location.





Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 5.** Photo shows an overview of the cut slope at the west of the location.



Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 6.** Photos show two large rills becoming gullies (left) and rill erosion and widespread pedestaling (right) on the western cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801404



Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 7.** Photos taken to the west of the battery show the cut slope on 9/30/2021 (left) and on 3/29/23 (right). Erosion has progressed to form a large rill on the slope. Note three sagebrush at top of slope for reference.



Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 8.** Photo shows an overview of the cut slope at the south of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801404



Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 9.** Photos show pedestal erosion throughout the cut slope at the south of the location.



Inspection Photos  
Location Name: Duggan/RWF 14-29  
Location ID: 429828



**Photo 10.** Photos show interim areas to the west (left) and east (right).

