

LARAMIE ENERGY LLC, NVega/1B Pad

Location # 334450



Location – Photo #01722

Wellheads – Photo #01723

LARAMIE ENERGY LLC, NVega/1B Pad

Location # 334450



Separators – Photo #01724



Tank Battery – Photo #01726

LARAMIE ENERGY LLC, NVega/1B Pad

Location # 334450



Gas Meter – Photo #01725



Cut Slope Erosion/Run-On to Location – Photo #01729

LARAMIE ENERGY LLC, NVega/1B Pad

Location # 334450



Lease Road Degradation – Photo #01732



Transport of Sediment/Lack of Stabilization – Photo #01733

LARAMIE ENERGY LLC, NVega/1B Pad

Location # 334450



Transport of Sediment/Lack of Stabilization – Photo #01734