

LARAMIE ENERGY LLC, NVega/3A Pad

Location # 334487



Location – Photo #01759

Wellheads – Photo #01761

LARAMIE ENERGY LLC, NVega/3A Pad

Location # 334487



Separators – Photo #01762



Tank Battery – Photo #01767

LARAMIE ENERGY LLC, NVega/3A Pad

Location # 334487



Gas Meter – Photo #01763



Missing Wildlife Protection – Photo #01765

LARAMIE ENERGY LLC, NVega/3A Pad

Location # 334487



Wildlife Screen – Photo #01764



Cut Slope Erosion/Run-off – Photo #01773

LARAMIE ENERGY LLC, NVega/3A Pad

Location # 334487



Site Degradation/Transport of Sediment – Photo #01770



Lease Road Degradation/Transport of Sediment – Photo #01776

LARAMIE ENERGY LLC, NVega/3A Pad

Location # 334487



Lack of Stabilization – Photo #01769