


LARAMIE ENERGY LLC, Gunderson/20-03 Pad

Location # 449070



Wellheads – Photo #01785



Separators – Photo #01787

LARAMIE ENERGY LLC, Gunderson/20-03 Pad

Location # 449070



Tank Battery – Photo #01789



ECD – Photo #01790



LARAMIE ENERGY LLC, Gunderson/20-03 Pad

Location # 449070



**Inadequate Chemical Secondary Containment –
Photo #01786**



Degradation/Sediment Transport – Photo #01794

LARAMIE ENERGY LLC, Gunderson/20-03 Pad

Location # 449070



**Lack of Stabilization w/ Inadequate Tracking BMP –
Photo #01791**



**Lack of Stabilization w/ Inadequate Tracking BMP –
Photo #01793**