

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



Colorado Oil and Gas Conservation Commission  
40.77317, -103.81506, 4580.0ft, 133°  
03/23/2023 11:55:30


**Photo 1 – Signs at Entrance**




Colorado Oil and Gas Conservation Commission  
40.772, -103.81599, 4569.7ft, 199°  
03/23/2023 11:56:18

**Photo 2 – Compressor**

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 3 – Separators – Unmarked Risers at Headers**



**Photo 4 – Unmarked Risers at Headers**



**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 5 – Compressor**




**Photo 6 – Rack**

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 7 – Unmarked Risers at Headers**




**Photo 8 – Unmarked Risers at Headers**



**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 9 – Produced Water Tanks**



**Photo 10 – Unmarked Risers at Headers**

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 11 – ECDs**



**Photo 12 – VRTs and VRU**



**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 13 – ECDs**



**Photo 14 – Tank Battery**

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 15 – LACT and Tank Battery**



**Photo 16 – Produced Water Tank**



**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 17 – Heater Treater and Instrumental Air Unit**



**Photo 18 – Unmarked Riser at Air Unit**

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 19 – Unmarked Risers at Headers**



**Photo 20 – Separators**



**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 21 – Pig Station**



**Photo 22 – Gas Sales Meter**

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 23 – Maintenance Tank**




**Photo 24 – Pig Station**



**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 25 – Gas Sales Meters**



**Photo 26 – Unmarked Riser at Gas Sales Meter**

**Inspection Photos**  
**Location Name: LD12-78HN PAD**  
**Location ID: 437863**



**Photo 27 – Signs at Entrance**

