



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Crude Oil Tanks - Content and Capacity Labels. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/28/2023

<b>Emergency Contact Number:</b>			
Comment:			Date:
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained Soil at Gas Engine Exhaust; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	04/28/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

<b>Equipment:</b>			
Type: Other	# 1		corrective date
Comment:	TA Wellhead		
Corrective Action:		Date:	

Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: [Shares berm with the Crude Oil Tanks](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	500 BBLs	STEEL AST		40.758260,-103.838850

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Paint**

Condition Adequate \_\_\_\_\_

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Venting:**

Yes/No NO \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flaring:**

Type \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 423026 Type: WELL API Number: 123-33493 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Crude Oil Tanks' Content and Capacity Labels. Stained Soil at Gas Engine Exhaust</a>	petrie	03/31/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304764	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6068577">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6068577</a>