

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW

Location ID: 334772



Photo #9411 From entrance to location.



Photo #9412 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW

Location ID: 334772



Photo #9413 Calibration cards not conspicuously posted.