

Inspection Photos
Location Name: UPRR 23 PAN AM L1
Location ID: 319929




Photo# 1 Crude Tank & P/W Tank.



Photo# 2 Meter & Separator.

Inspection Photos
Location Name: UPRR 23 PAN AM L1
Location ID: 319929



Photo# 3 Pump Jack.