

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Mar 31, 2023 at 9:22:08 AM  
CO



Mar 31, 2023 at 9:22:11 AM  
CO

Photo # 3892 From entrance to location

Photo # 3893 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 3894 Location



Photo # 3895 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 3896 Location



Photo # 3897 Containment liner needs maintenance



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



**Photo # 3901 Containment liner needs maintenance**



**Photo # 3902 Tank label illegible**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



**Photo # 3904 Meter calibration info not conspicuously posted**



**Photo # 3905 Meter calibration info not conspicuously posted**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 3906 Debris



Photo # 3907 Debris



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 3921 Debris



Photo # 3922 Debris



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



**Photo # 3914 Debris & barbed wire (wildlife hazard)**



**Photo # 3908 Barbed wire (wildlife hazard)**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



**Photo # 3909 Barbed wire (wildlife hazard)**



**Photo # 3910 Barbed wire (wildlife hazard)**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 3911 Barbed wire (wildlife hazard)



Photo # 3912 Barbed wire (wildlife hazard)

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



**Photo # 3913 Barbed wire (wildlife hazard)**



**Photo # 3916 Barbed wire (wildlife hazard)**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



**Photo # 3918 Barbed wire (wildlife hazard)**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources