

# Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 311677

Location Name: HARRIS-67S94W/5SWNE

Inspection Document #: 702801406

Garfield County, CO

SWNE Section 5 T7S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HARRIS-67S94W/5SWNE  
Location ID: 311677



**Photo 1.** Photo show an overview of northern production areas.



**Photo 2.** Photo shows an overview of southern production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801406

Inspection Photos  
Location Name: HARRIS-67S94W/5SWNE  
Location ID: 311677



**Photo 3.** Photo shows an unmarked anchor to the west of the wells.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801406

Inspection Photos  
Location Name: HARRIS-67S94W/5SWNE  
Location ID: 311677



**Photo 4.** Photo taken from the northern edge of the pad shows the northeastern portion of the pad has not been reclaimed. Photo also shows storage of equipment.



**Photo 5.** Photo taken from the northern edge of the pad shows the northwestern portion of the pad has not been reclaimed.



Inspection Photos  
Location Name: HARRIS-67S94W/5SWNE  
Location ID: 311677



Photo 6. Photo shows unreclaimed areas at the north of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801406

Inspection Photos  
Location Name: HARRIS-67S94W/5SWNE  
Location ID: 311677



**Photo 7.** Photo shows an overview of the cut slope at the east of the location.



**Photo 8.** Photo shows an overview of the cut slope to the south of the location behind the separators.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801406

Inspection Photos  
Location Name: HARRIS-67S94W/5SWNE  
Location ID: 311677



Photo 9. Photo shows equipment stored throughout the location.