

Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335066

Location Name: SAVAGE-66S94W/32SWNE

Inspection Document #: 702801408

Garfield County, CO

SWNE Section 32 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-66S94W/32SWNE
Location ID: 335066



Photo 1. Photo shows an overview of western/lower production area.



Photo 2. Photo shows an overview of eastern/upper production area.

Inspection Photos
Location Name: SAVAGE-66S94W/32SWNE
Location ID: 335066



Photo 3. Photos show production areas.



Inspection Photos
Location Name: SAVAGE-66S94W/32SWNE
Location ID: 335066



Photo 4. Photos show unmarked anchors to the south of the wells.

Inspection Photos
Location Name: SAVAGE-66S94W/32SWNE
Location ID: 335066



Photo 5. Photo shows an unmarked anchors to the south of the wells.



Photo 6. Photo shows an unmarked anchors to the north of the wells. Photo also shows where a perimeter stormwater berm has been blown out.



Inspection Photos

Location Name: SAVAGE-66S94W/32SWNE

Location ID: 335066




Photo 7. Photos taken to the north of the wells show multiple areas where the perimeter stormwater berm has been blown out.

Inspection Photos
Location Name: SAVAGE-66S94W/32SWNE
Location ID: 335066



Photo 8. Photos show interim areas to the northeast (left) and west (right).

