

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location ID: 335295



Mar 31, 2023 at 10:13:59 AM
CO



Mar 31, 2023 at 10:14:06 AM
CO

Photo # 3924 From entrance to location

Photo # 3925 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location ID: 335295



Photo # 3926 Location



Photo # 3927 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location ID: 335295



Photo # 3928 Location



Photo # 3933 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location ID: 335295



Photo # 3934 Meter calibration info not conspicuously posted



Photo # 3937 Containment liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location ID: 335295



Photo # 3940 Containment liner needs maintenance



Photo # 3938 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location ID: 335295



**Photo # 3947 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 3948 Lack of stabilization/Insufficient tracking
BMP's**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 534-20 pad

Location ID: 335295



**Photo # 3955 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 3924 Lack of stabilization/Insufficient tracking
BMP's**