

Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335225

Location Name: SAVAGE-66S94W/33NWNE

Inspection Document #: 702801412

Garfield County, CO

NWNE Section 33 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-66S94W/33NWNE
Location ID: 335225



Photo 1. Photos taken from the entrance shows an overview of the upper/northern portion of the location (left) and production areas (right). Note lack of stabilization/compaction (ruts).

Inspection Photos
Location Name: SAVAGE-66S94W/33NWNE
Location ID: 335225



3/29/23
+39.488279, -107.890693
255° W

Photo 2. Photo shows an unmarked anchor to the southeast of the wells.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801412

Inspection Photos
Location Name: SAVAGE-66S94W/33NWNE
Location ID: 335225



Photo 3. Photo shows the southern/lower production area. Note the unstabilized access road and erosion and sediment deposition to the south/left of the road.



Inspection Photos
Location Name: SAVAGE-66S94W/33NWNE
Location ID: 335225



Photo 4. Photo shows erosion at the south of the location.

Inspection Photos
Location Name: SAVAGE-66S94W/33NWNE
Location ID: 335225



Photo 5. Photos show lack of stabilization of the access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801412